SALES ORDER

5 meter

NO. 1072

DATE 4/24.86

CUSTOMER'S NO.

TO [redacted] WEST 10TH STREET SUIT 100 [redacted] 7474

SHIP TO SAME

SALESPERSON	DATE REQUIRED	SHIP VIA	F.O.B.	TERMS
SIGRID	S.A.P.	SMITH/TR	G-FORCE	PAID

	ORDERED	DESCRIPTION	PRICE	PER	AMOUNT
1					
2	12441	EXTRUSION MAST			291.00
3		EXTRA DRILLING			20.00
4					
5	2/98301	PIVOT-CHIP	@1.25		2.50
6		WIRE COVER			
7					313.50
8		I had to get a new mast after a storm flipped my cat and the mast was bent.			
9					
10					
11		FREIGHT			53.13
12					
13		ALLEN WE WERE UNABLE			
14		TO DRILL YOUR MAST. REASON			
15		BEING WE ARE UNSURE ON Hardware			
16		ON YOUR MAST NOW. There has			
17		been changes in the hardware over			
18		the years. Going by your old			
19		mast you should have no problem			
20		drilling the extrusion yourself. Thanks			
			TOTAL		$ 366.63

BUYER

TOPS FORM 3790
LITHO IN U.S.A.

ORIGINAL